



Feed Through Side



POWER LINE DIRECTION



Feed Through Side




POWER LINE DIRECTION



Pipe Side

Drill 2X 0.281" dia holes thru' on box base plate and unistrut accordingly



Pipe Side

